

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, Washington 98101-3140

ALC 3 1 2014

OFFICE OF COMPLIANCE AND ENFORCEMENT

IDG130013

JERRY CHAPMAN, HATCHERY MGR
NIAGARA SPRINGS FISH HATCHERY
2131 NIAGARA SPRINGS ROAD
NIAGARA SPRINGS FISH
WENDELL, ID 83355

Re:

National Pollutant Discharge Elimination System (NPDES)

Discharge Monitoring Reports (DMRs)

Dear Permittee:

Enclosed is a supply of preprinted Discharge Monitoring Reports (DMR). The preprinted forms reflect effluent limits, monitoring, and reporting requirements currently in your permit.

Please note the following important items:

Please take time to review these forms. The permittee is responsible for reporting exactly as the NPDES permit requires, even if the preprinted DMRs are not complete or correct.

If you did not receive a complete supply of DMRs, please make a master copy of a DMR and adjust the dates for future submittals.

It is necessary to fill in the number of excursions, frequency of analysis and sample type in their appropriate columns.

It is necessary to date the DMR and sign every page.

If all the DMRs prepared for a particular month are not used (e.g., a specific outfall does not have a discharge), please note (no discharge) on the DMR, sign and submit it with the other completed DMR forms.

Fill in every blank space on the form. This will prevent your facility from appearing on the violation's list for non-reporting.

Mail the original copy of the completed DMRs to this address:

U.S. EPA, Region 10 1200 Sixth Avenue, Suite 900 Mail Stop: OCE-133 Seattle, WA 98101

If you have any questions on how the permit was translated to the preprinted DMRs, please call

Ramona Castro at (206) 553-6318. For compliance questions for municipals, contact Maria Lopez at (208) 378-5616; for compliance questions for mining, contact Eva DeMaria at (206) 553-1970, and for compliance questions for aquaculture, contact Chris Gebhardt at (206) 553-0253.

Sincerely

/s/

Data-Entry Team

Enclosures



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, Washington 98101-3140

DEC 30 2013

OFFICE OF COMPLIANCE AND ENFORCEMENT

NIAGARA SPRINGS FISH HATCHERY 2131 NIAGARA SPRINGS ROAD WENDELL, ID 83355

IDG 130013

Re:

National Pollutant Discharge Elimination System (NPDES) Discharge Monitoring Reports (DMRs)

Dear Permittee:

Enclosed is a supply of preprinted Discharge Monitoring Reports (DMR). The preprinted forms reflect effluent limits, monitoring, and reporting requirements currently in your permit.

Please note the following important items:

Please take time to review these forms. The permittee is responsible for reporting exactly as the NPDES permit requires, even if the preprinted DMRs are not complete or correct.

If you did not receive a complete supply of DMRs, please make a master copy of a DMR and adjust the dates for future submittals.

It is necessary to fill in the number of excursions, frequency of analysis and sample type in their appropriate columns.

It is necessary to date the DMR and sign every page.

If all the DMRs prepared for a particular month are not used (e.g., a specific outfall does not have a discharge), please note (no discharge) on the DMR, sign and submit it with the other completed DMR forms.

Fill in every blank space on the form. This will prevent your facility from appearing on the violation's list for non-reporting.

Mail the original copy of the completed DMRs to the following address:

U.S. EPA, Region 10 1200 Sixth Avenue, Suite 900 Mail Stop: OCE-133 Seattle, WA 98101

To the state of th	



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, WA 98101-3140 DEC 1 2 2012

OFFICE OF COMPLIANCE AND ENFORCEMENT

IDG130013 JERRY CHAPMAN, HATCHERY MGR NIAGARA SPRINGS FISH HATCHERY 2131 NIAGARA SPRINGS ROAD NIAGARA SPRINGS FISH WENDELL, ID 83355

Re: National Pollutant Discharge Elimination System (NPDES) Discharge Monitoring

Reports (DMRs)

Dear Permittee:

Enclosed is a supply of preprinted Discharge Monitoring Reports (DMR). The preprinted forms reflect effluent limits, monitoring, and reporting requirements currently in your permit.

Please note the following important items:

Please take time to review these forms. The permittee is responsible for reporting exactly as the NPDES permit requires, even if the preprinted DMRs are not complete or correct.

If you did not receive a complete supply of DMRs, please make a master copy of a DMR and adjust the dates for future submittals.

It is necessary to fill in the number of excursions, frequency of analysis and sample type in their appropriate columns.

It is necessary to date the DMR and sign every page.

If all the DMRs prepared for a particular month are not used (e.g., a specific outfall does not have a discharge), please note (no discharge) on the DMR, sign and submit it with the other completed DMR forms.

Fill in every blank space on the form. This will prevent your facility from appearing on the violation's list for non-reporting.

Mail the original copy of the completed DMRs to the following address:

Attention: OCE-133 U.S. EPA, Region 10 1200 Sixth Avenue, Suite 900 Seattle, WA 98101 If you have any questions on how the permit was translated to the preprinted DMRs, please call

Ramona Castro at (206) 553-6318. For compliance questions for municipals, contact David Domingo at (206) 553-0531; for compliance questions for mining, contact Eva DeMaria at (206) 553-1970, and for compliance questions for aquaculture, contact Chris Gebhardt at (206) 553-0253.

Since Jus

Sincerely,

Diane Davis

Environmental Protection Specialist

Enclosures